



# ORIGINAL BENDER



The value of the 180K resistor varies in original units.

Enclosure should be grounded.

Original units did this by connecting the Level pot body to lug 1.